



DUCHY *of* CORNWALL
HARBOUR OFFICE ST MARY'S ISLES OF SCILLY TR21 0HU
Telephone: (01720) 422768 Email hm@stmarys-harbour.co.uk
Harbour Master: Dale Clark

LNtM No. 16/17

BACON BUOY OUT OF POSITION

Valid From: 16th October 2017

Mariners are advised that the port hand buoy (Bacon Buoy) at the entrance to St. Mary's Harbour – 49 55.22'N 006 19.25W Fl.(4) R 5s – has come adrift from its moorings and is out of position.

LNtMs in force: 1/17

All LNtMs are available online at www.stmarys-harbour.co.uk

Dale Clark,
Harbour Master,
St Mary's Harbour,
Isles of Scilly