



DUCHY *of* CORNWALL
HARBOUR OFFICE ST MARY'S ISLES OF SCILLY TR21 0HU
Telephone: (01720) 422768 Email hm@stmarys-harbour.co.uk
Harbour Master: Dale Clark

LOCAL NOTICE TO MARINERS
No. 02/19

ST MARY'S HARBOUR

DAMAGE TO OUTER BERTH FENDERING

Mariners are advised that the most seaward fender of the berthing face of St Mary's Harbour outer berth has sustained damage. Vessel operators are requested to avoid using this fender as far as is reasonably achievable for the safe manoeuvring of their vessel.

08/16 - Installation of seasonal water inlet at Pelistry Bay (St Mary's)

All LNTMs are available online at www.stmarys-harbour.co.uk

Dale Clark,
Harbour Master,
St Mary's Harbour,
Isles of Scilly